Oil Field Environmental Incident Summary

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC
Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: EN-KMJ URAN- 154-93-2734H-8

Field Name: ROBINSON LAKE Well File #: 27064

Date Incident:2/27/2016Time Incident:11:00Facility ID Number:County:MOUNTRAILTwp: 154Rng: 93Sec: 27Qtr:

Location Description:

Submitted By: Alex Beach Received By:

Contact Person: Troy Brunsell

3015 16th Street SW, Suite 20

Minot, ND 58701

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:1 MileDistance Nearest Water Well:1 Mile

Type of Incident: Tank Leak

 Release Contained in Dike: Yes - Within Dike
 Reported to NRC: No

 Spilled
 Units
 Recovered
 Units
 Followup
 Units

 Oil
 2.6
 Barrels
 2.6
 barrels

 Brine
 0

0

Description of Other Released Contaminant:

Inspected: Written Report Received: 5/4/2016 Clean Up Concluded: 4/28/2016

Risk Evaluation:

Other

There is no immediate risk to report at this time.

Areal Extent:

Potential Environmental Impacts:

There are no potential environmental impacts to report at this time. All of the released fluid remained onsite.

Action Taken or Planned:

The impacted material will be cleaned up and disposed of at an approved waste disposal facility.

Wastes Disposal Location: The impacted material will be cleaned up and disposed of at an approved waste disposal facility.

Agencies Involved:

Updates

Date: 2/29/2016 Status: Reviewed - Assigned to Other Agency Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the release remained on location. NDIC has oversight.